



General Surface Cleaning Instructions

The steps shown below outline the **general procedures** to follow when cleaning a surface in preparation of a bird control installation. These steps below outline the **minimum precautions that should be taken**. If heavy accumulations of bird waste is present, additional safety precautions will be required.


1. Wear a minimum of protective gloves, eye protection and a respiratory mask to guard against harmful bacteria that may be present in bird droppings.




2. Treat the surface and debris with a disinfectant. Read and follow the directions on the container.




3. After treatment, remove the bird waste and debris from the surface. Follow all local regulation for disposal.




4. Wash the surface thoroughly to remove any remaining filth.



5. Re-treat the surface with the disinfectant to remove any remaining germs, bacteria, or odors.



6. The end result should be a clean, dry and odor free surface that is ready for the installation of bird/ climbing animal control.



Nixalite® of America Inc.
1025 16th Avenue East Moline, IL. 61244
Experts In Architectural Bird Control Since 1950

Phone: 800.624.1189 or 309.755.8771

Fax: 800.624.1196 or 309.755.0077

Email: birdcontrol@nixalite.com

Web: www.nixalite.com

Where the World Shops for Humane Bird and Animal Control.

